

St Phillips Church

Side portico

St Phillips Place

FFL Roof + 51.713

FFL Fourth + 48.373

FFL Third + 45.448

FFL Second + 42.523

FFL First + 39.598

Ground + 35.348

+ 35.700

Powder coated louvres

Samafil roofing

Powder coated lintol

Aluminium powder coated windows

Powder coated columns

Stone Rainscreen

Powder coated chs handrail

TCS cladding

Powder coated louvres

Powder coated curtain walling

Powder coated louvres

Aluminium powder coated windows

TCS cladding

Powder coated handrail

Powder coated metalwork

TCS cladding

Glass balustrade

Stone cills

TCS cladding

Powder coated signage zone

TCS clad plinth

Proposed Development

TCS clad plinth

Retail entrance

Powder coated steel lintol

Redundant Bar

Apartment entrance

Glass Canopy

Redundant Bank

CHAPEL STREET ELEVATION